



- NOTES:
1. THE EXOTHERMIC WELD CAP SHALL COMPLETELY COVER THE WIRE CONNECTION.
 2. TAPE SHALL BE USED TO SECURE THE WELD CAP TO THE PIPE.
 3. THE WELD CAP SHALL BE ORIENTED SO THAT THE WIRE SHALL BE RUN IN THE LONGITUDINAL DIRECTION OF THE PIPE.

EXOTHERMIC WELD CAP INSTALLATION

NTS



TOWN OF FREDERICK
STANDARDS & SPECIFICATIONS

700-11